




160875_p.jpg: Lily-W132 (#223) on EVB LILY-W1 carrier-board - top view

 Examiner:
 Paul NEUFELD
 Report Number:
 F160785E3

 Date of issue:
 27.06.2016
 Order Number:
 16-110785

 page 1 of 9
 page 1 of 9






160875_q.jpg: Lily-W132 (#122B) with temporary antenna connector on EVB LILY-W1 carrier-board – top view

 Examiner:
 Paul NEUFELD
 Report Number:
 F160785E3

 Date of issue:
 27.06.2016
 Order Number:
 16-110785

 page 2 of 9
 page 2 of 9





160875_r.jpg: Lily-W131 (#215) on EVB LILY-W1 carrier-board - top view

 Examiner:
 Paul NEUFELD
 Report Number:
 F160785E3

 Date of issue:
 27.06.2016
 Order Number:
 16-110785

 page 3 of 9
 page 3 of 9





160785_s.jpg: Lily-W132 (#223) with shielding on EVB LILY-W1 carrier-board close up – top view

 Examiner:
 Paul NEUFELD
 Report Number:
 F160785E3

 Date of issue:
 27.06.2016
 Order Number:
 16-110785

 page 4 of 9
 page 4 of 9





160785_t.jpg: Lily-W132 (#122B) with temporary antenna connector and shielding on EVB LILY-W1 carrier-board close up – top view

 Examiner:
 Paul NEUFELD
 Report Number:
 F160785E3

 Date of issue:
 27.06.2016
 Order Number:
 16-110785

 page 5 of 9
 page 5 of 9






160785_u.jpg: Lily-W131 (#215) with shielding on EVB LILY-W1 carrier-board close up – top view

 Examiner:
 Paul NEUFELD
 Report Number:
 F160785E3

 Date of issue:
 27.06.2016
 Order Number:
 16-110785

 page 6 of 9
 page 6 of 9





160785_i.jpg: Lily-W131/132 on EVB LILY-W1 carrier-board - bottom view

 Examiner:
 Paul NEUFELD
 Report Number:
 F160785E3

 Date of issue:
 27.06.2016
 Order Number:
 16-110785

 page 7 of 9





160785_a.jpg: Linux board cB0962* - top view


 Examiner:
 Paul NEUFELD
 Report Number:
 F160785E3

 Date of issue:
 27.06.2016
 Order Number:
 16-110785

 page 8 of 9
 page 8 of 9

^{*} The module visible in the picture is not part of this test report and was not active during any of the tests that were performed for this test report.





160785_b.jpg: Linux board cB0962 - bottom view

 Examiner:
 Paul NEUFELD
 Report Number:
 F160785E3

 Date of issue:
 27.06.2016
 Order Number:
 16-110785

 page 9 of 9
 page 9 of 9