




Test setup – antenna port conducted measurements

 Examiner:
 Bernward ROHDE
 Report Number:
 F181014E7

 Date of issue:
 08/09/2018
 Order Number:
 18-111014
 page 1 of 9






Test setup PT4-B301#3 - Test setup fully anechoic chamber

 Examiner:
 Bernward ROHDE
 Report Number:
 F181014E7

 Date of issue:
 08/09/2018
 Order Number:
 18-111014
 page 2 of 9






Test setup PT2-B312#8 - Test setup fully anechoic chamber

 Examiner:
 Bernward ROHDE
 Report Number:
 F181014E7

 Date of issue:
 08/09/2018
 Order Number:
 18-111014

 page 3 of 9






Test setup fully anechoic chamber

 Examiner:
 Bernward ROHDE
 Report Number:
 F181014E7

 Date of issue:
 08/09/2018
 Order Number:
 18-111014

 page 4 of 9





Test setup fully anechoic chamber 30 MHz - 1 GHz

 Examiner:
 Bernward ROHDE
 Report Number:
 F181014E7

 Date of issue:
 08/09/2018
 Order Number:
 18-111014
 page 5 of 9






Test setup open area test site 30 MHz - 1 GHz

 Examiner:
 Bernward ROHDE
 Report Number:
 F181014E7

 Date of issue:
 08/09/2018
 Order Number:
 18-111014
 page 6 of 9






Test setup fully anechoic chamber 1 – 12 GHz

 Examiner:
 Bernward ROHDE
 Report Number:
 F181014E7

 Date of issue:
 08/09/2018
 Order Number:
 18-111014
 page 7 of 9





Test setup fully anechoic chamber 12 – 26.5 GHz

 Examiner:
 Bernward ROHDE
 Report Number:
 F181014E7

 Date of issue:
 08/09/2018
 Order Number:
 18-111014
 page 8 of 9





Test setup AC mains

 Examiner:
 Bernward ROHDE
 Report Number:
 F181014E7

 Date of issue:
 08/09/2018
 Order Number:
 18-111014
 page 9 of 9