


170297_E8_13.jpg: EUT #403 (int ant) on not marketed eval board - top view

 Examiner:
 Bernward ROHDE
 Report Number:
 F162097E6

 Date of issue:
 26.02.2018
 Order Number:
 16-112097
 page 1 of 8






170297_E8_14.jpg: EUT #403 (onboard antenna) on not marketed eval board – close-up

 Examiner:
 Bernward ROHDE
 Report Number:
 F162097E6

 Date of issue:
 26.02.2018
 Order Number:
 16-112097
 page 2 of 8






170297_E8_15.jpg: EUT #403 (onboard antenna) on not marketed eval board – bottom view

 Examiner:
 Bernward ROHDE
 Report Number:
 F162097E6

 Date of issue:
 26.02.2018
 Order Number:
 16-112097
 page 3 of 8






170297_E8_23.jpg: EUT (onboard antenna)
- bottom side

 Examiner:
 Bernward ROHDE
 Report Number:
 F162097E6

 Date of issue:
 26.02.2018
 Order Number:
 16-112097

page 4 of 8






170297_E8_10.jpg: EUT #403 with antenna trace design on not marketed eval board – top view

 Examiner:
 Bernward ROHDE
 Report Number:
 F162097E6

 Date of issue:
 26.02.2018
 Order Number:
 16-112097

 page 5 of 8






170297_E8_11.jpg: EUT #403 with antenna trace design on not marketed eval board – close-up

 Examiner:
 Bernward ROHDE
 Report Number:
 F162097E6

 Date of issue:
 26.02.2018
 Order Number:
 16-112097

page 6 of 8






170297_E8_12.jpg: EUT #403 with antenna trace design on not marketed eval board – bottom view

 Examiner:
 Bernward ROHDE
 Report Number:
 F162097E6

 Date of issue:
 26.02.2018
 Order Number:
 16-112097
 page 7 of 8





170297_E8_22.jpg: EUT #403 - bottom view

 Examiner:
 Bernward ROHDE
 Report Number:
 F162097E6

 Date of issue:
 26.02.2018
 Order Number:
 16-112097

page 8 of 8