




Test setup fully anechoic chamber 30 MHz - 1 GHz

 Examiner:
 Bernward ROHDE
 Report Number:
 F190149E3

 Date of issue:
 13.03.2019
 Order Number:
 19-110149
 page 1 of 6






Test setup fully anechoic chamber

 Examiner:
 Bernward ROHDE
 Report Number:
 F190149E3

 Date of issue:
 13.03.2019
 Order Number:
 19-110149
 page 2 of 6






Test setup fully anechoic chamber 30 MHz - 1 GHz

 Examiner:
 Bernward ROHDE
 Report Number:
 F190149E3

 Date of issue:
 13.03.2019
 Order Number:
 19-110149
 page 3 of 6





Test setup fully anechoic chamber 1 – 12 GHz

 Examiner:
 Bernward ROHDE
 Report Number:
 F190149E3

 Date of issue:
 13.03.2019
 Order Number:
 19-110149
 page 4 of 6





Test setup fully anechoic chamber 12 – 18 GHz

 Examiner:
 Bernward ROHDE
 Report Number:
 F190149E3

 Date of issue:
 13.03.2019
 Order Number:
 19-110149
 page 5 of 6





Test setup fully anechoic chamber 18 – 26.5 GHz

 Examiner:
 Bernward ROHDE
 Report Number:
 F190149E3

 Date of issue:
 13.03.2019
 Order Number:
 19-110149
 page 6 of 6