

Peak Output Power Modulation: GFSK Tx frequency: 2402MHz



27.OCT.2014 09:03:08 Date:


Modulation: GFSK Tx frequency: 2441MHz



Date: 27.OCT.2014 09:07:21




Modulation: GFSK Tx frequency: 2480MHz



Date: 27.OCT.2014 09:07:55




Modulation: $\pi/4$ -DQPSK Tx frequency: 2402MHz



Date: 27.OCT.2014 09:41:02


Modulation: $\pi/4$ -DQPSK Tx frequency: 2441MHz



Date: 27.OCT.2014 09:41:57



Modulation: $\pi/4$ -DQPSK Tx frequency: 2480MHz



Date: 27.OCT.2014 09:42:30




Modulation: 8DPSK Tx frequency: 2402MHz



Date: 27.OCT.2014 10:08:07


Modulation: 8DPSK Tx frequency: 2441MHz



Date: 27.OCT.2014 10:07:33



Modulation: 8DPSK Tx frequency: 2480MHz




Date: 27.OCT.2014 10:06:51




Band Edge Compliance

Tx frequency: 2402MHz (radiated measurement)



Vertical Polarization






Horizontal Polarization




Tx frequency: 2480MHz (radiated measurement)




Vertical Polarization






Horizontal Polarization

<u>Duty cycle correction factor</u> Tx mode: Hopping in 79 channels








Only one pulse is found in 100ms time. Other pulses were verified that they were from the side band due to 1MHz RBW.

27.OCT.2014 10:30:06



Spurious at 1.6GHz



Comment: test print
Date: 4.NOV.2014 16:01:22