
Test setup photographs





Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Dynastream Innovations, Inc. Models: C782M4IB, C782M5IB

Test #:110815B

Test to: CFR47 Parts 2, 15.249, RSS-210

File: TSup 1823

FCC ID: O6R1823 IC: 3797A-1823 SN: 8990000000012 Date: September 1, 2011 Page 1 of 1