

Report No. : FD9D1639-02

Setup Photographs

<Conducted Emission> Mode 2



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XSX-1013 Page Number : B1 of B4
Report Issued Date : Mar. 09, 2010
Report Version : Rev. 01







Report No. : FD9D1639-02

Side View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XSX-1013 Page Number : B2 of B4
Report Issued Date : Mar. 09, 2010
Report Version : Rev. 01





<Radiated Emission>

Mode 1



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XSX-1013 Page Number : B3 of B4
Report Issued Date : Mar. 09, 2010
Report Version : Rev. 01

Report No.: FD9D1639-02





Report No. : FD9D1639-02



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XSX-1013 Page Number : B4 of B4
Report Issued Date : Mar. 09, 2010
Report Version : Rev. 01