
FCC ID: XTE-ULPAP310 IC: 8655A-ULPAP310

Report No.: SD72111752-1115



America



WARNING: FCC/IC ID numbers valid for Dual Latency System configurations only.

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference.
- (2) This device must accept any interference received, including interference that may cause undesired operation.

ID Label



FCC ID: XTE-ULPAP310 IC: 8655A-ULPAP310

Report No.: SD72111752-1115





Label Location on cabinet