


## Report No.: FR961822B

## Appendix B. Setup Photographs

## <Conducted Emission>

Mode 1



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : B1 of B4 Report Issued Date: Oct. 29, 2009 Report Version : Rev. 01



Report No.: FR961822B



Side View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : B2 of B4
Report Issued Date : Oct. 29, 2009
Report Version : Rev. 01




Report No.: FR961822B

## <Radiated Emission>



Front View




Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : B3 of B4
Report Issued Date : Oct. 29, 2009
Report Version : Rev. 01







Remote View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : B4 of B4
Report Issued Date : Oct. 29, 2009
Report Version : Rev. 01