


Report No. : FA961822

Appendix D. Product Photos



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Report Issued Date : Oct. 29, 2009
Report Version : Rev. 01



Antenna Location:



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Report Issued Date : Oct. 29, 2009
Report Version : Rev. 01

Report No. : FA961822



Appendix E. Test Setup Photos



Bottom of the DUT with Phantom 0 cm Gap <Steady Roller Bearing>

Bottom of the DUT with Phantom 0 cm Gap <Tilted Roller Bearing>

Report No. : FA961822

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Report Issued Date: Oct. 29, 2009

Report Version : Rev. 01