


t Report No. : FR961822A

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : B1 of B4
Report Issued Date : Oct. 29, 2009
Report Version : Rev. 01





Report No.: FR961822A




Side View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : B2 of B4
Report Issued Date : Oct. 29, 2009
Report Version : Rev. 01



<Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : B3 of B4
Report Issued Date : Oct. 29, 2009
Report Version : Rev. 01

Report No.: FR961822A



Report No.: FR961822A



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : B4 of B4
Report Issued Date : Oct. 29, 2009
Report Version : Rev. 01