3. Internal Photographs of EUT

Model Name: Beam


Report No.: EP961822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 15 of 38
Issued Date : Oct. 29, 2009
Report Version : Rev. 01




Report No.: EP961822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 16 of 38 Issued Date : Oct. 29, 2009 Report Version : Rev. 01




Report No.: EP961822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 17 of 38 Issued Date : Oct. 29, 2009 Report Version : Rev. 01




Report No.: EP961822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 18 of 38
Issued Date : Oct. 29, 2009
Report Version : Rev. 01




Report No.: EP961822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 19 of 38 Issued Date : Oct. 29, 2009 Report Version : Rev. 01




WLAN + Bluetooth Module



Page Number : 20 of 38 Issued Date : Oct. 29, 2009 Report Version : Rev. 01




Report No.: EP961822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 21 of 38
Issued Date : Oct. 29, 2009
Report Version : Rev. 01




Report No.: EP961822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 22 of 38
Issued Date : Oct. 29, 2009
Report Version : Rev. 01




Report No.: EP961822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 23 of 38
Issued Date : Oct. 29, 2009
Report Version : Rev. 01








Page Number : 24 of 38
Issued Date : Oct. 29, 2009
Report Version : Rev. 01






Page Number : 25 of 38 Issued Date : Oct. 29, 2009 Report Version : Rev. 01








Page Number : 26 of 38
Issued Date : Oct. 29, 2009
Report Version : Rev. 01






Page Number : 27 of 38
Issued Date : Oct. 29, 2009
Report Version : Rev. 01



Report No.: EP961822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 28 of 38 Issued Date : Oct. 29, 2009 Report Version : Rev. 01




WWAN Module Model Name: Beam



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 29 of 38
Issued Date : Oct. 29, 2009
Report Version : Rev. 01




WWAN Module Model Name: Beam



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 30 of 38 Issued Date : Oct. 29, 2009 Report Version : Rev. 01




WWAN Module Model Name: Beam



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 31 of 38 Issued Date : Oct. 29, 2009 Report Version : Rev. 01




WWAN Module Model Name: Beam




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 32 of 38 Issued Date : Oct. 29, 2009 Report Version : Rev. 01

Bluetooth Antenna Model Name: Beam




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 33 of 38
Issued Date : Oct. 29, 2009
Report Version : Rev. 01

Bluetooth Antenna Model Name: Beam




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 34 of 38 Issued Date : Oct. 29, 2009 Report Version : Rev. 01


WLAN Antenna Model Name: Beam



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 35 of 38
Issued Date : Oct. 29, 2009
Report Version : Rev. 01








Page Number : 36 of 38
Issued Date : Oct. 29, 2009
Report Version : Rev. 01

WWAN Main Antenna Model Name: Beam



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 37 of 38
Issued Date : Oct. 29, 2009
Report Version : Rev. 01

WWAN Aux. Antenna Model Name: Beam



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XTT-BEAMATT Page Number : 38 of 38 Issued Date : Oct. 29, 2009 Report Version : Rev. 01