

Date: May 27, 2016

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

Attention: Application Examiner/ Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: XU8TEW740APBO

To The Commission:

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by TRENDnet, Inc. will establish a new FCC ID under TRENDnet, Inc. grantee code for purpose of marketing. The original grant to (Original Company FCC ID: SCDOW141000001) will remain in effect.

An authorization letter by LanReady Technologies Inc.is attached.

Per 2.933(b)

- 1. The original identification is SCDOW141000001
- 2. The original grant date is 2013/8/9
- 3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
- 4. The original test results are applicable and representative of this changed device.
- 5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

- Cover Letter
- External Photos
- FCC ID label format and location

Sincerely,

Applicant: TRENDnet, Inc.

Address: 20675 Manhattan Place.

Torrance, CA 90501

Signature:

Name: Wen Tsai

Job Title: Senior Product Manager Email: w.tsai@trendnet.com

Tel. **310-961-5500**

20675 Manhattan Place Torrance CA 90501 U.S.A. Tel: 310-961-5500 Fax: 310-961-5511 www.TRENDnet.com