

20675 Manhattan Place, Torrance, CA 90501, USA

2014-10-06

Federal Communications Commission Laboratory Division 7435 Oakland Mills Road Columbia, MD 21046

Attention: Office of Engineering and Technology

Re: KDB Inquiry Tracking Number 584444

Incorrect FCC ID Granted - Dismissal Request

The application filing for FCC ID XU8TEW21BRM was incorrect due to a typographical error in the FCC ID. No device has been labeled with the FCC ID XU8TEW21BRM and has never been sold or marketed anywhere. We are requesting FCC ID XU8TEW21BRM be dismissed and removed from the FCC website as an approved product.

Your help with dismissing FCC ID XU8TEW21BRM is greatly appreciated. Thank you.

Sincerely,

.....

Wen Tsai /Sr. Product Manager

TRENDNET, Inc.

TEL.: (310)961-5500 ext.5474

FAX: (310)961-5511

w.tsai@trendnet.com