

420 Stevens Ave, Suite 320 Solana Beach, CA 92075

January 19, 2010

Timco Engineering, Inc. 849 NW State Road 45 Newberry, FL 32669 888-472-2424

Test Report Cover Letter

To whom it may concern,

This letter certifies that per § 2.933 Change in identification of equipment:

(1) The original identification used on the equipment prior to the change in identification.

FCC ID: X2U-SHAMU-PCIE, certified 12-29-2009 (manufacturer Via Telecom, part no. Shamu_PCIe)

- **(2)** The date of the original grant of the equipment authorization. FCC ID: X2U-SHAMU-PCIE, certified 12-29-2009
- (3) How the equipment bearing the modified identification differs from the original equipment.

The device previously certified under FCC ID: X2U-SHAMU-PCIE, certified 12-29-2009 (manufacturer Via Telecom, part no. Shamu_PCIe) is identical to the device with FCC ID: XU9-FW2770P (manufacturer Fusion Wireless, part no. FW2770p) The two devices are identical. No hardware, software, packaging or printed circuit board changes have been made

(4) Whether the original test results continue to be representative of and applicable to the equipment bearing the changed identification. Yes, the original tests results continue to be representative of and applicable to the equipment bearing the changed identification.

Sincerely,

David W. Carey President and CEO Fusion Wireless

Dand N. Ca