American Certification Body Inc. 6731 Whittier Ave, Suite C110 McLean, VA22101

Date: 15.04.2013

Subject: Equipment certified under wrong FCC ID

Dear Sirs,

We want to get changed the FCC ID: XUY0YX0YU02037 in the original application, granted on 04/12/2013.

The original application contains the wrong FCC ID.

The correct FCC ID is:

XUY0YX0MU02037

Martin Zikmund

Y SOFT Corporation Podnikatelska 2902/4 61200 Brno

Czech Republic

11

Y Soft Corporation, a.s. DIČ: CZ26197740, www.ysoft.com U Kněžské louky 2151/18, 130 00 Praha 3