



| | | | |
|--|--------------|--------------|--------------------------------------|
| Test Date | 2018/03/26 | Temp./Hum. | 25°C/54% |
| Mode | 802.11n-HT20 | UNII Band | II-2C |
| | | Frequency | TX 5700MHz |
| Cable Loss | 1.74dB | Test Voltage | AC 120V, 60Hz (via AC/DC Adapter) |
| Simultaneous Factor 10 log(n) (Note: "n" is antenna number) | | 6.02 | |







| | | | |
|--|---------------|------------|--------------------------------------|
| Test Date | 2018/03/26~29 | Temp./Hum. | 25°C/54% |
| Mode | 802.11n-HT20 | UNII Band | III |
| Cable Loss | 1.74dB | Frequency | TX 5745MHz |
| Simultaneous Factor 10 log(n) (Note: "n" is antenna number) | | | AC 120V, 60Hz (via AC/DC Adapter) |
| | | | 6.02 |






| | | | |
|--|---------------|------------|--------------------------------------|
| Test Date | 2018/03/26~29 | Temp./Hum. | 25°C/54% |
| Mode | 802.11n-HT20 | UNII Band | III |
| Cable Loss | 1.74dB | Frequency | TX 5785MHz |
| Simultaneous Factor 10 log(n) (Note: "n" is antenna number) | | | AC 120V, 60Hz (via AC/DC Adapter) |
| | | | 6.02 |






| | | | |
|--|---------------|------------|--------------------------------------|
| Test Date | 2018/03/26~29 | Temp./Hum. | 25°C/54% |
| Mode | 802.11n-HT20 | UNII Band | III |
| Cable Loss | 1.74dB | Frequency | TX 5825MHz |
| Simultaneous Factor 10 log(n) (Note: "n" is antenna number) | | | AC 120V, 60Hz (via AC/DC Adapter) |
| | | | 6.02 |





| | | | |
|--|----------------|--------------|--------------------------------------|
| Test Date | 2018/03/26~28 | Temp./Hum. | 25°C/54% |
| Mode | 802.11ac-VHT40 | UNII Band | I |
| | | Frequency | TX 5190MHz |
| Cable Loss | 1.74dB | Test Voltage | AC 120V, 60Hz (via AC/DC Adapter) |
| Simultaneous Factor 10 log(n) (Note: "n" is antenna number) | | 6.02 | |




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




| | | | |
|--|----------------|--------------|--------------------------------------|
| Test Date | 2018/03/26~28 | Temp./Hum. | 25°C /54% |
| Mode | 802.11ac-VHT40 | UNII Band | I |
| | | Frequency | TX 5230MHz |
| Cable Loss | 1.74dB | Test Voltage | AC 120V, 60Hz (via AC/DC Adapter) |
| Simultaneous Factor 10 log(n) (Note: "n" is antenna number) | | 6.02 | |






| | | | |
|--|----------------|--------------|--------------------------------------|
| Test Date | 2018/03/26 | Temp./Hum. | 25°C/54% |
| Mode | 802.11ac-VHT40 | UNII Band | II-2A |
| | | Frequency | TX 5270MHz |
| Cable Loss | 1.74dB | Test Voltage | AC 120V, 60Hz (via AC/DC Adapter) |
| Simultaneous Factor 10 log(n) (Note: "n" is antenna number) | | 6.02 | |





| | | | |
|--|----------------|--------------|--------------------------------------|
| Test Date | 2018/03/26 | Temp./Hum. | 25°C/54% |
| Mode | 802.11ac-VHT40 | UNII Band | II-2A |
| | | Frequency | TX 5310MHz |
| Cable Loss | 1.74dB | Test Voltage | AC 120V, 60Hz (via AC/DC Adapter) |
| Simultaneous Factor 10 log(n) (Note: "n" is antenna number) | | 6.02 | |






| | | | |
|--|----------------|--------------|--------------------------------------|
| Test Date | 2018/03/26 | Temp./Hum. | 25°C/54% |
| Mode | 802.11ac-VHT40 | UNII Band | II-2C |
| | | Frequency | TX 5510MHz |
| Cable Loss | 1.74dB | Test Voltage | AC 120V, 60Hz (via AC/DC Adapter) |
| Simultaneous Factor 10 log(n) (Note: "n" is antenna number) | | 6.02 | |





| | | | |
|--|----------------|--------------|--------------------------------------|
| Test Date | 2018/03/26 | Temp./Hum. | 25°C/54% |
| Mode | 802.11ac-VHT40 | UNII Band | II-2C |
| Cable Loss | 1.74dB | Frequency | TX 5550MHz |
| | | Test Voltage | AC 120V, 60Hz (via AC/DC Adapter) |
| Simultaneous Factor 10 log(n) (Note: "n" is antenna number) | | 6.02 | |





Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303

| | | | |
|--|----------------|--------------|--------------------------------------|
| Test Date | 2018/03/26 | Temp./Hum. | 25°C/54% |
| Mode | 802.11ac-VHT40 | UNII Band | II-2C |
| | | Frequency | TX 5670MHz |
| Cable Loss | 1.74dB | Test Voltage | AC 120V, 60Hz (via AC/DC Adapter) |
| Simultaneous Factor 10 log(n) (Note: "n" is antenna number) | | 6.02 | |





| | | | |
|--|----------------|------------|--------------------------------------|
| Test Date | 2018/03/26~28 | Temp./Hum. | 25°C/54% |
| Mode | 802.11ac-VHT40 | UNII Band | III |
| Cable Loss | 1.74dB | Frequency | TX 5755MHz |
| Test Voltage | | | AC 120V, 60Hz (via AC/DC Adapter) |
| Simultaneous Factor 10 log(n) (Note: "n" is antenna number) | | | 6.02 |





| | | | |
|--|----------------|------------|--------------------------------------|
| Test Date | 2018/03/26~28 | Temp./Hum. | 25°C/54% |
| Mode | 802.11ac-VHT40 | UNII Band | III |
| Cable Loss | 1.74dB | Frequency | TX 5795MHz |
| Simultaneous Factor 10 log(n) (Note: "n" is antenna number) | | | AC 120V, 60Hz (via AC/DC Adapter) |
| | | | 6.02 |





| | | | |
|--|--|------------|------------|
| Test Date | 2018/03/26 | Temp./Hum. | 25°C/54% |
| Mode | 802.11ac-VHT80 | UNII Band | I |
| Cable Loss | 1.74dB | Frequency | TX 5210MHz |
| Simultaneous Factor 10 log(n) (Note: "n" is antenna number) | Test Voltage AC 120V, 60Hz (via AC/DC Adapter) | | |
| | | | 6.02 |



