Trane US, Inc. 6200 Troup Highway Tyler TX 75707

2014-08-01

Equipment Autorisation Division Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

Subject: Class II permissive change Request

FCC ID: XVR-CONT8501 Granted on: 04/02/2014

To whom may concern:

Pursuant to CRF Section 2.1043, Trane US, Inc. requests a Class II permissive change

The product has below changes:

- 1. R609 populate 0 odm resistance, R610 change to DNP
- 2. R943 populate 103AT NTC
- 3. D406 change to zener diode
- 4. C805, Q803, Q804, R817, R818, R819, R820, R821 change to DNP
- 5. R627 change component parameter, from 470R to 3R
- 6. R813 change component size ,from 5.1k/0402 to 5.1k/1206
- 7. Add SMT E-Cap C656 (47uF,50V,6.3*7.5mm Size), C649 change to DNP
- 8. C804, C807 change component parameter, from 0.01 uF/0402 to 0.001 uF/0402
- 9. C806 component change, from 22uF/1210 to 0.22uF/0805
- 10. R627: replace 0805 with 1210
- 11. R813: replace 5.1K/1206 with 5.11K/1206
- 12. Add two resistors 100K/0603,R842 ,R843
- 13. R823 change to 6.20 ohm, 5%, 1/4W
- 14. R830, R832 change to 20K/1206.
- 15. R824, R829 change component size to 1206.
- 16. D804, D615 change to SIG.
- 17. R833 change to 3.32K/0603.
- 18. Q802,Q806,Q808,Q809 change to MMBTA56LT1G
- 19. Q801, Q805, Q807 change to MMBTA06LT1G.
- 20. RV801 change to V68MLA1206NH
- 21. R832, R828, R821, R826, R825, R834, R814, R827, R835, R815 change component size to 0603.
- 22. add 0603 size ferrite bead L704 and L705 ,BLM18AG102SN1D
- 23. Revise PIN11 & PIN12 of J701 grounded type.
- 24. Removed R609, R610.

All of above revise are not relative to the RF circuit.

Trane US, Inc. 6200 Troup Highway Tyler TX 75707

Dated this _/	Day of 08/01/20	14 /
Ву:	I Juli	James Ford Johnson
-	Signature	Printed
Title:	Systems Test Engineer	·
On behalf of :	Trane US,	Inc.
Telephone:	903-581-3200	