

Figure 7: Measurement set-up for conducted measurement acc. to following sections of the report 1076-11-EE-11-PB005: 4.1.1; 4.1.2; 4.2; 4.3; 4.4 and 4.5.5



Figure 8: Measurement set-up for radiated measurement < 30 MHz acc. following sections of the report 1076-11-EE-11-PB005: 4.5.1




Figure 9: Measurement set-up for radiated measurement > 30 MHz and < 1 GHz acc. following sections of the report 1076-11-EE-11-PB005: 4.5.2 and 4.6.1



Figure 10: Measurement set-up for radiated measurement > 1 GHz acc. following sections of the report 1076-11-EE-11-PB005: 4.5.3; 4.5.4 and 4.6.2



Figure 11: Measurement set-up for conducted measurement of disturbance voltage acc. following section of the report 1076-11-EE-11-PB005: 4.7 and 4.8