
# **INTERTEK TESTING SERVICE**

Report No.: HK12070785-4

# Configuration Photographs Worst-Case Line-Conducted Emissions (Front View)

Model: DR-9055RL




# **INTERTEK TESTING SERVICE**

Report No.: HK12070785-4

# Configuration Photographs Worst-Case Line-Conducted Emissions (Rear View)

Model: DR-9055RL




FCC ID: XW3DR9055RL

# **INTERTEK TESTING SERVICE**

Report No.: HK12070785-4

# Configuration Photographs Worst-Case Line-Conducted Emissions (Side View)

Model: DR-9055RL



FCC ID: XW3DR9055RL