#### **FUNCTIONAL DESCRIPTION**

#### **Temperature and out Sensor**

Convert the air temperature from physical quantity to resistance.

### **Crystal Oscillator**

A very stable crystas accurate pulses and feed into MCU as master clock.

# **Battery**

In-series by battery 2 units of 1.5V supply energy to whole circuit system.

## **Low Battery Detect**

When the power voltge low to specify value, detect circuit is active and the LCD display the mark of the low battery.

#### **RF Transmit**

Modulate temperature data to 433.92MHz signal & transmit form air.X1,Q1,Q2 and associated circuit act as 433.92MHz Oscillator.

## **MCU(Microprogrammed Control Unit)**

2-bit MCU consist of all software,logic control and memory for system calculation and hardware control purpose.

# **Temperature sensor**

Refer to BLOCK DIAGRAM,sensor PT3-312-1 will insert into the center of the meat,it will detect the temperature and send to transmitter,when the value changed,the transmitter will send to receiver.