

Radio House, St Andrew's Road, Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000 Fax: + 44 (0) 1223 879000

sepura.com

Internal Photographs

For

XX6STP9280

1







Going further in critical communications





Radio House, St Andrew's Road, Cambridge CB4 1GR, England.

Tel: +44 (0) 1223 876000 Fax: +44 (0) 1223 879000

sepura.com

Contents

XX6STP9280	3
XX6STP9280 WITHOUT HEATSINK	4
XX6STP9280 WITHOUT CANS	5
	_
XX6STP9280 LCD SIDE	6
XX6STP9280 LCD SIDE LESS FRAME	7
AAOST F3200 LCD SIDE LESS FRAIVIE	<i>1</i>
XX6STP9280 LCD SIDE LESS CANS	8













Radio House, St Andrew's Road, Cambridge CB4 1GR, England.

Tel: +44 (0) 1223 876000 Fax: +44 (0) 1223 879000

sepura.com

XX6STP9280 With Heatsink









Going further in critical communications





Radio House, St Andrew's Road, Cambridge CB4 1GR, England.

Tel: +44 (0) 1223 876000 Fax: +44 (0) 1223 879000

sepura.com

XX6STP9280 Without Heatsink



4





Going further in critical communications






Radio House, St Andrew's Road, Cambridge CB4 1GR, England.

Tel: +44 (0) 1223 876000 Fax: +44 (0) 1223 879000

sepura.com

XX6STP9280 Without Cans



5











Radio House, St Andrew's Road, Cambridge CB4 1GR, England.

Tel: +44 (0) 1223 876000 Fax: +44 (0) 1223 879000

sepura.com

XX6STP9280 LCD Side


















Radio House, St Andrew's Road, Cambridge CB4 1GR, England.

Tel: +44 (0) 1223 876000 Fax: +44 (0) 1223 879000

sepura.com

XX6STP9280 LCD side less frame















Radio House, St Andrew's Road, Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000 Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9280 LCD side without cans

