

Sepura plc

Radio House, St Andrew's Road, Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000 Fax: + 44 (0) 1223 879000

sepura.com

TUV BABT TCB/FCB Octagon House Concorde Way Segensworth North Fareham Hampshire PO15 5RL

Date: 9th September 2014

FCC CFR 47 Part 15B RSS-Gen, Clause 4.9

Data Port connection in relation to the following products:

FCC ID XX6SRG3900XN IC:8739A-SRG3900XN

ATTESTATION: I attest that the data ports on the above product are only used for the attachment of the user interface (console) and are also used during the manufacturing and initial configuration / programming of the product at which time the product is inoperable. The end user is unable to use the product as a Class B peripheral. In addition, there are no RF ports on these connectors.

Sincerely, J. Wood

Company Officer: Steve Wood

Telephone Number: +44 (01223) 877354

Email: <u>steve.wood@Sepura.com</u>

Position: Verification Engineering Team leader









