

## Sepura plc

Radio House, St Andrew's Road, Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000 Fax: + 44 (0) 1223 879000

sepura.com

Date: 2014-01-14

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division

7435 Oakland Mills Road

Columbia, Maryland 21046

Subject: Extended Frequency Justification

Dear Sir/Madam,

The DMR Repeater with FCC ID: XX6SER8040 was designed to operate in the frequency bands 400~470MHz

To aid equipment authorization in other countries which accept the United States FCC Grant for Certification, Sepura plc is requesting that the FCC lists the frequencies 400~470MHz, under FCC Rule Parts 22 and 90 on the FCC Grant.

Sepura plc attests that the DMR Repeater will not be marketed to USA users with the frequency band which is not allowed by the rule part 22 and 90. Per the FCC's KDB634817 guidance, as an alternative to listing the exact frequencies, we acknowledge that it's a violation of the FCC Rules if this device operates on unauthorized frequencies.

Frequency Range (MHz)	FCC Rule Part
406.1-450 MHz	FCC Part 90
450-454MHz	FCC Part 90
454-455MHz	FCC Part 22
456-460MHz	FCC Part 22/ FCC Part 90
460-462.5375MHz	FCC Part 90
462.7375-467.5375MHz	FCC Part 90
467.7357-470MHz	FCC Part 90

٠

Also, equipment programming is the responsibility of Authorized Service Personnel, the DMR Repeater complies with 47 CFR Part 90.203(e), in that the operator cannot directly program the transmit frequencies using the normally accessible external controls.

Sincerely:

8. Wood

Company Officer:

Steve Wood

Telephone Number:

+44 (01223) 877354

Email:

steve.wood@sepura.com

Position:

Verification Engineering Team leader









