

## Sepura plc

Radio House, St Andrew's Road, Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000 Fax: + 44 (0) 1223 879000

sepura.com

TUV BABT TCB/FCB Octagon House Concorde Way Segensworth North Fareham Hampshire PO15 5RL

Date: 11<sup>th</sup> December 2013

FCC CFR 47 Part 15B RSS-Gen, Clause 4.9

Data Port connection in relation to the following products:

FCC ID XX6STP9040 and FCC ID XX6STP9240 IC:8739A-STP9040 and IC:8739A-STP9240

ATTESTATION: I attest that the data port on the above products is only of use during the manufacturing and initial configuration / programming of the product and during this process the product is inoperable. The end user is unable to use the product as a Class B peripheral. In addition, there are no RF ports on this connector.

Sincerely,

Company Officer: Steve Wood

Telephone Number: +44 (01223) 877354

Email: <u>steve.wood@Sepura.com</u>

Position: Verification Engineering Team leader









