Test report No. : 29DE0043-HO-A
Page : 14 of 49
Issued date : January 26, 2010
FCC ID : XXJDMS001

#### **APPENDIX 1: Photographs of test setup**

# Conducted Emission Type-1



Photo 1



Photo 2

### UL Japan, Inc.

#### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 29DE0043-HO-A
Page : 15 of 49
Issued date : January 26, 2010
FCC ID : XXJDMS001

## Conducted Emission Type-2



Photo 1




Photo 2

#### UL Japan, Inc.

#### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 29DE0043-HO-A
Page : 16 of 49
Issued date : January 26, 2010
FCC ID : XXJDMS001

# Radiated Spurious Emission Type-1







Photo 2

#### UL Japan, Inc.

#### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Test report No. : 29DE0043-HO-A
Page : 17 of 49
Issued date : January 26, 2010
FCC ID : XXJDMS001

#### Worst Case Position (Horizontal: X-axis/ Vertical: Y-axis)

# Type-1 X-axis



Y-axis



**Z**-axis



**Head Office EMC Lab.** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 29DE0043-HO-A
Page : 18 of 49
Issued date : January 26, 2010
FCC ID : XXJDMS001

# **Radiated Spurious Emission Type-2**



Photo 1



Photo 2

#### UL Japan, Inc.

#### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

: 29DE0043-HO-A Test report No. Page : 19 of 49 **Issued date** : January 26, 2010 FCC ID : XXJDMS001

# Worst Case Position (Horizontal: X-axis/ Vertical: Y-axis) Type-2 X-axis



Y-axis



Z-axis



**Head Office EMC Lab.** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 : +81 596 24 8124 Facsimile