


KES Co., Ltd.3701, 40, Simin-daero 365beon-gil,
Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea
Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr

Test report No.: KES-RF-18T0038 Page (57) of (58)


Appendix B. Test setup photos





KES Co., Ltd.3701, 40, Simin-daero 365beon-gil,
Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea
Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr

Test report No.: KES-RF-18T0038 Page (58) of (58)



Note.: Radiated testing was performed with the EUT in worst-case Y orientation.

The end of test report.