	H609 MB PC	B V1.0	WRITER	
			CHECK	
			APPROVE	
quantity	materiel number	manufacturer	spec and type of pruduct of the manufacturer	remark
3	CC15641P0MU0	GRM1555C1H1R0CZ01D	Murata	
5	CC15641P8MU0	GRM1555C1H1R8CZ01D	Murata	
4	CC15642P7MU0	GRM1555C1H2R7CZ01D	Murata	
1	CC15644P7MU0	GRM1555C1H4R7CZ01D	Murata	
3	CC136410PMU0	GRM1555C1H100JZ01D	Murata	
1	CC136415PMU0	GRM1555C1H150JZ01D	Murata	
2	CC136418PMU0	GRM1555C1H180JZ01D	Murata	
3	CC136422PMU0	GRM1555C1H220JZ01D	Murata	
6	CC136433PMU0	GRM1555C1H330JZ01D	Murata	
1	CC136439PMU0	GRM1555C1H390JZ01D	Murata	
3	CC136447PMU0	GRM1555C1H470JZ01D	Murata	
1	CC1364101MU0	GRM1555C1H101JZ01D	Murata	
2	CC1261221MU0	GRM155R71H221KA01D	Murata	
1	CC1261471MU0	GRM155R71H471KA01D	Murata	
10	CC1261102MU0	GRM155R71H102KA01D	Murata	
2	CC1231103MU0	GRM155R71E103KA01D	Murata	
2	CC1232473MU0	GRM155R71C473KA01D	Murata	
33	CC1222104MU0	GRM155R71A104KA01D	Murata	
1	CC2222105MU0	GRM188R61A105KA61D	Murata	
39	CC1212105MU0	GRM155R60J105KE19D	Murata	
2	CC2212225MU0	GRM188R60J225KE19D	Murata	
3	CC2212475MU0	GRM188R60J475KE19D	Murata	
4	CC3112106MU0	GRM21BR60J106ME19L	Murata	
3	CC3112106MU1	GRM219R60J106KE19L	Murata	
1	CT4116106NI0	F930J107MBA	Nichicon	
2	LI143N9SL000	SDCL1005C3N9ST(f),	Sunlord	
1	LI144N7MU000	LQG15HS4N7S02D	Murata	
2	LI145N6SL000	SDCL1005C5N6STDF	Sunlord	
1	LI1115NMU000	LQG15HS15NJ02D	Murata	
2	LI1122NSL000	SDCL1005C22NJTDF	Sunlord	
1	LI1147NMU000	LQG15HS47NJ02D	Murata	
1	LI1156NSL000	SDCL1005C56NJT(f),	Sunlord	·
2	LI11121MU000	LQG15HSR12J02D	Murata	
1	LI33103MU000	LQM18FN100M00D	MURATA	
<u>·</u> 1	LI43472MU000	LQH32CN4R7M53	Murata	
· ·		2		
20	RC1200R0YA00	RC0402JR-070RL	Yageo	
1	RC3110R2YA00	RC0805FR-070R2L	Yageo	
2	RC1205R1YA00	RC0402JR-075R1L	Yageo	
2	RC22015RYA00	RC0603JR-0715RL	Yageo	
3	RC12018RYA00	RC0402JR-0718RL	Yageo	
8	RC12033RYA00	RC0402JR-0733RL	Yageo	
1	RC120221YA00	RC0402JR-07220RL	Yageo	
4	RC120271YA00	RC0402JR-07270RL	Yageo	
11	RC120331YA00	RC0402JR-07330RL	Yageo	
1	RC120471YA00	RC0402JR-07470RL	Yageo	
1	RC120681YA00	RC0402JR-07680RL	Yageo	

	DC420402VA00	DC0402 ID 074KI	Vanaa	
11	RC120102YA00	RC0402JR-071KL	Yageo	
1	RC120202YA00	RC0402JR-072KL	Yageo	
2	RC120222YA00	RC0402JR-072K2L	Yageo	
1	RC120332YA00	RC0402JR-073K3L	Yageo	
2	RC120362YA00	RC0402JR-073K6L	Yageo	
2	RC120472YA00	RC0402JR-074K7L	Yageo	
6	RC120103YA00	RC0402JR-0710KL	Yageo	
2	RC120333YA00	RC0402JR-0733KL		
2	RC120513YA00	RC0402JR-0751KL	Yageo	
7	RC120104YA00	RC0402JR-07100KL	Yageo	
1	RC120154YA00	RC0402JR-07150KL	Yageo	
1	RC120105YA00	RC0402JR-071M	Yageo	
2	BF14121MU000	BLM15AG121SN1D	Murata	
2	BF24471MU000	BLM18PG471SN1D,	Murata	
7	BF14102SL000	HZ1005K102T(f)	Sunlord	
6	RV140500EP00	B72590T0140L060	EPCOS	
1	U047030AL000	AON4703	ALPHA&OMEGA	
1	D052030CJ000	RB520S30-2/TR	江苏长江	
1	Q010120DI000	DMG1012T-7	DIODES	
	11074000DE000	DE7400		
1	U071630RF000	RF7163	RFMD	
1	U085330MS000	MSW8533_LF	MSTAR	
1	U042100NX000	AER04210HN1WMS00	NXP	
1	U058680RD000	RDA5868+	RDA	
1	U058880RD000	,RDA5888	RDA	
1	U071128SP300	S71WS128PC0HF3TR	SPANSION	
1	X0260000TX00	7M26000314	тхс	
1	X032768SE000	SSP-T7-F	0-11	
1			ISelko	
	X027000ND000	EXS00A-CS02111	Seiko NDK	
1	X027000ND000	EXS00A-CS02111	NDK	
<u>1</u> 1	X027000ND000 U095000SO000	EXS00A-CS02111 HMD950T-T		
	X027000ND000	EXS00A-CS02111	NDK soshin	
1	X027000ND000 U095000SO000 U010030ED000	EXS00A-CS02111 HMD950T-T TS1003	NDK soshin EDISON	
1 3	X027000ND000 U095000SO000 U010030ED000 U031570SG000	EXS00A-CS02111 HMD950T-T TS1003 SGM3157YC6/TR	NDK soshin EDISON SGMICRO	
1 3	X027000ND000 U095000SO000 U010030ED000 U031570SG000 JCU05254LI00	EXS00A-CS02111 HMD950T-T TS1003 SGM3157YC6/TR UAF95-05254-1500	NDK soshin EDISON SGMICRO Linkconn	
1 3 1	X027000ND000 U095000SO000 U010030ED000 U031570SG000 JCU05254LI00 JCS02241JS00	EXS00A-CS02111 HMD950T-T TS1003 SGM3157YC6/TR UAF95-05254-1500 WKSM022-4101	NDK soshin EDISON SGMICRO Linkconn JTC0NN(杰顺)	
1 3 1 1	X027000ND000 U095000SO000 U010030ED000 U031570SG000 JCU05254LI00 JCS02241JS00 JCA03057CS00	EXS00A-CS02111 HMD950T-T TS1003 SGM3157YC6/TR UAF95-05254-1500 WKSM022-4101 03-0003-3057	NDK soshin EDISON SGMICRO Linkconn JTCONN(杰顺) 昌讯	
1 3 1 1 1	X027000ND000 U095000SO000 U010030ED000 U031570SG000 JCU05254LI00 JCS02241JS00 JCA03057CS00 F019600EP000	EXS00A-CS02111 HMD950T-T TS1003 SGM3157YC6/TR UAF95-05254-1500 WKSM022-4101 03-0003-3057 B39202-B9403-K610	NDK soshin EDISON SGMICRO Linkconn  JTCONN (杰顺) 昌讯 EPCOS murata	
1 3 1 1 1 1	X027000ND000 U095000SO000 U010030ED000 U031570SG000  JCU05254LI00  JCS02241JS00 JCA03057CS00 F019600EP000 F050000MU000	EXS00A-CS02111 HMD950T-T TS1003 SGM3157YC6/TR UAF95-05254-1500 WKSM022-4101 03-0003-3057 B39202-B9403-K610 SAFEA881MFL0F00R12	NDK soshin EDISON SGMICRO Linkconn JTCONN(杰顺) 昌讯 EPCOS	
1 3 1 1 1 1 1 1	X027000ND000 U095000SO000 U010030ED000 U031570SG000  JCU05254LI00  JCS02241JS00 JCA03057CS00 F019600EP000 F050000MU000 F095000EP000 H609MBPCB100	EXS00A-CS02111 HMD950T-T TS1003 SGM3157YC6/TR UAF95-05254-1500 WKSM022-4101 03-0003-3057 B39202-B9403-K610 SAFEA881MFL0F00R12	NDK soshin EDISON SGMICRO Linkconn  JTCONN (杰顺) 昌讯 EPCOS murata	
1 3 1 1 1 1 1 1 1	X027000ND000 U095000SO000 U010030ED000 U031570SG000  JCU05254LI00  JCS02241JS00 JCA03057CS00 F019600EP000 F05000MU000 F095000EP000 H609MBPCB100 PBZH917BB000	EXS00A-CS02111 HMD950T-T TS1003 SGM3157YC6/TR UAF95-05254-1500 WKSM022-4101 03-0003-3057 B39202-B9403-K610 SAFEA881MFL0F00R12	NDK soshin EDISON SGMICRO Linkconn  JTCONN (杰顺) 昌讯 EPCOS murata	
1 3 1 1 1 1 1 1 1 1 1	X027000ND000 U095000SO000 U010030ED000 U031570SG000  JCU05254LI00  JCS02241JS00 JCA03057CS00 F019600EP000 F095000EP000 H609MBPCB100 PBZH917BB000 PBZH917BT000	EXS00A-CS02111 HMD950T-T TS1003 SGM3157YC6/TR UAF95-05254-1500 WKSM022-4101 03-0003-3057 B39202-B9403-K610 SAFEA881MFL0F00R12	NDK soshin EDISON SGMICRO Linkconn  JTCONN (杰顺) 昌讯 EPCOS murata	
1 3 1 1 1 1 1 1 1 1 1 1	X027000ND000 U095000S0000 U010030ED000 U031570SG000  JCU05254LI00  JCS02241JS00 JCA03057CS00 F019600EP000 F05000MU000 F095000EP000 H609MBPCB100 PBZH917BB000 PBZH917BT000 PBZH917BT000 PBZH609TV000	EXS00A-CS02111 HMD950T-T TS1003 SGM3157YC6/TR UAF95-05254-1500 WKSM022-4101 03-0003-3057 B39202-B9403-K610 SAFEA881MFL0F00R12	NDK soshin EDISON SGMICRO Linkconn  JTCONN (杰顺) 昌讯 EPCOS murata	
1 3 1 1 1 1 1 1 1 1 1	X027000ND000 U095000SO000 U010030ED000 U031570SG000  JCU05254LI00  JCS02241JS00 JCA03057CS00 F019600EP000 F050000MU000 F095000EP000 H609MBPCB100 PBZH917BT000 PBZH917BT000 PBZH917RF000	EXS00A-CS02111 HMD950T-T TS1003 SGM3157YC6/TR UAF95-05254-1500 WKSM022-4101 03-0003-3057 B39202-B9403-K610 SAFEA881MFL0F00R12 B39182B9500L310	NDK soshin EDISON SGMICRO Linkconn JTCONN (杰顺) 昌讯 EPCOS murata Epcos	
1 3 1 1 1 1 1 1 1 1 1 1	X027000ND000 U095000S0000 U010030ED000 U031570SG000  JCU05254LI00  JCS02241JS00 JCA03057CS00 F019600EP000 F050000MU000 F095000EP000 PBZH917BB000 PBZH917BT000 PBZH917RF000 SM-14J 32.768KHZ 1	EXS00A-CS02111 HMD950T-T TS1003 SGM3157YC6/TR UAF95-05254-1500 WKSM022-4101 03-0003-3057 B39202-B9403-K610 SAFEA881MFL0F00R12 B39182B9500L310	NDK soshin EDISON SGMICRO Linkconn JTCONN (杰顺) 昌讯 EPCOS murata Epcos	
1 3 1 1 1 1 1 1 1 1 1 1	X027000ND000 U095000SO000 U010030ED000 U031570SG000  JCU05254LI00  JCS02241JS00 JCA03057CS00 F019600EP000 F050000MU000 F095000EP000 H609MBPCB100 PBZH917BT000 PBZH917BT000 PBZH917RF000	EXS00A-CS02111 HMD950T-T TS1003 SGM3157YC6/TR UAF95-05254-1500 WKSM022-4101 03-0003-3057 B39202-B9403-K610 SAFEA881MFL0F00R12 B39182B9500L310	NDK soshin EDISON SGMICRO Linkconn JTCONN (杰顺) 昌讯 EPCOS murata Epcos	

EXSO0A-CS01422	26MHZ, crystal	NDK	
X1E000021031400	26MHZ, crystal	EPSON	
MC3117	27MHZ, crystal	瑞信半导体	