INTERTEK TESTING SERVICE


Report No.: HK11040905-2


Equipment Photographs

Model: TRFM915

(External)

External Antenna





INTERTEK TESTING SERVICE

Report No.: HK11040905-2

Equipment Photographs

Model: TRFM915

(External)

Trace Antenna

