

775 Montague Expressway Milpitas, CA 95035 Tel: 408-526-1188 Fax: 408-526-1088

Email: TCB@siemic.com

FCC CLASS II PERMISSIVE CHANGE REQUEST LETTER

Reason for Amendment (current / obsolete)	Revision History		
	From	То	Approved Date
Initial Release (current)	1.0	1.0	Feb-20-2012

Outform Ltd

FCC Class II Permissive Change Request Letter

Date: Jan. 25, 2016

To FCC:

RE: FCC Permissive II Change Request for Company: Lightcomm Technology Co.,Ltd. FCC ID: Y34-UITBSM


We are submitting an application for a class II permissive change to the FCC approval of the Company name: **Outform Ltd**, product description: MID (FCC: **Y34-UITBSM**, Original Grant Date: Nov. 04, 2015). The transmitter module itself has not changed. The LED drives board has changed version number from V1.1 to V1.3,here are the changes:


A:add CN2A/PH2.0 * 4 pin DC input socket

B: add CN4A/PH2.0 * 6 pin backlit output socket

C: Increases the distance L1 inductance between PIN4 feet square copper foil and copper foil, in order to prevent the L1 - PIN4 short-circuit

Original:





Sincerely,

Client's signature

Client's name / title: Eyal Shani/ General Manager

Contact information / address

R405, East, Buliding 203, Tai Ran Industrial Zone, Chengongmiao, Futian, Shenzhen, China

Eyal Shani