

Internal Photo (Model: PRIME 4)
















Page 6 / 31 Report No.: T190220N01 Ref. No.: T170809N03 Rev. 00









Page 7 / 31 **Report No.:** T190220N01 Ref. No.: T170809N03 Rev. 00









Page 8 / 31 Report No.: T190220N01 Ref. No.: T170809N03 Rev. 00









Page 9 / 31 **Report No.:** T190220N01 Ref. No.: T170809N03 Rev. 00














Report No.: T190220N01 Ref. No.: T170809N03 Page 11 / 31 Rev. 00
















Report No.: T190220N01 Ref. No.: T170809N03 Page 13 / 31









Page 14 / 31 Report No.: T190220N01 Ref. No.: T170809N03 Rev. 00









Page 15 / 31 **Report No.:** T190220N01 Ref. No.: T170809N03 Rev. 00








Report No.: T190220N01 Ref. No.: T170809N03 Page 16 / 31 Rev. 00




















Report No.: T190220N01 Ref. No.: T170809N03 Page 19 / 31






















Page 22 / 31 **Report No.:** T190220N01 Ref. No.: T170809N03 Rev. 00















Report No.: T190220N01 Ref. No.: T170809N03 Page 24 / 31 Rev. 00




2 05 05 01 00 to 90 07 09 04 05 05 01



Report No.: T190220N01 Ref. No.: T170809N03 Page 25 / 31









Report No.: T190220N01 Ref. No.: T170809N03 Page 27 / 31 Rev. 00

Solution Photo







Page 28 / 31


Report No.: T190220N01 Ref. No.: T170809N03 Rev. 00








 Report No.:
 T190220N01
 Ref. No.:
 T170809N03
 Page Rev.
 29 / 31 Rev.








 Report No.:
 T190220N01
 Ref. No.:
 T170809N03
 Page
 30 / 31







 Report No.:
 T190220N01
 Ref. No.:
 T170809N03
 Page Rev.
 31 / 31 Rev.

