

## **ASSA ABLOY Hospitality**

12.08.2016

FCC ID: Y7V-4827610CC1

## **Application for Limited Modular Approval**

The LCU 5350 contains completely self-contained radio frequency transmitter devices. It includes a 2.4GHz BLE transceiver and a 13.56MHz RFID transceiver. LCU 5350 is t is typically incorporated into a door lock or wall reader.

- (i) The radio elements of the 2.4GHz BLE transceiver part have its own shielding. The radio part of the 13.56MHz RFID transceiver does not have its own shielding
- (ii) The LCU 5350 does not have any modulation inputs, or data inputs that affect radio transmission.
- (iii) The LCU 5350 has internal 5.0V and 3.3V voltage regulators for supplying power to the transmitter.
- (iv) The LCU 5350 has permanently attached antennas
- (v) The LCU 5350 has been tested in a standalone configuration
- (vi) The LCU 5350 is equipped with a permanently affixed label, displaying its own FCC identification number. The LCU 5350 is a part of a door lock, delivered in modules to the end customer. Before the lock is assembled onto / into the door at site, the labels on all modules with FCC ID are fully visible.
- (vii) The specific rule parts that apply to the complete transmitter are 15.225 and 15.247.
- (viii) The applicable RF exposure requirements is 47CFR 1.1310(e) Table 1 (B) Limits for the General Population.

Date: 12<sup>th</sup> of August, 2016

Bjørn Kolstad Manager Testlab

On behalf of: ASSA ABLOY Hospitality AS

Telephone: +4769245000