

ASSA ABLOY Hospitality

03.04.2017

FCC ID: Y7V-683081150C1

Application for Modular Approval

Requirement	Compliance reference
(i) The radio elements must have the radio frequency circuitry shielded. Physical components and tuning capacitor(s) may be located external to the shield, but must be on the module assembly	Yes: Shielding is provided by a metal cover over the RF circuitry.
(ii) The module must have buffered modulation/data inputs to ensure that the device will comply with Part 15 requirements with any type of input signal	Yes: All modulation and data inputs are buffered by circuitry on the transmitter chip.
(iii) The module must contain power supply regulation on the module	Yes: The module has internal 3.0V voltage regulator.
(iv) The module must contain a permanently attached antenna, or contain a unique antenna connector, and be marketed and operated only with specific antenna(s), per Sections 15.203, 15.204(b), 15.204(c), 15.212(a), 2.929(b)	Yes: The module has permanently attached integrated PCB antenna.
(v) The module must demonstrate compliance in a stand-alone configuration	Yes: The module has been tested in a standalone configuration.
(vi) The module must be labelled with its permanently affixed FCC ID label, or use an electronic display (See KDB Publication 784748 about labelling requirements)	Yes: The module is equipped with a permanently affixed label, displaying its own FCC identification number. The module is a part of a door lock, delivered in modules to the end customer. Before the lock is assembled onto / into the door at site, the labels on all modules with FCC ID are fully visible.
(vii) The module must comply with all specific rules applicable to the transmitter including all the conditions provided in the integration instructions by the grantee	Yes: The module complies fully with the operating requirements of rule 15.247 as demonstrated in the test report exhibit.
(viii) The module must comply with RF exposure requirements	Yes: The module complies with RF exposures requirements according to the RF Exposure exhibits.



Date: 3rd of April, 2017

Bjørn Kolstad Manager Testlab

On behalf of: ASSA ABLOY Hospitality AS

Telephone: +4769245000