Test report No. : 11374628H-B-R1 Page : 13 of 15

: September 7, 2016

Issued date FCC ID : Y8PFJ17-1

APPENDIX 3: Photographs of test setup

Radiated Emission (Below 1GHz)



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11374628H-B-R1

Page : 14 of 15

Issued date : September 7, 2016 FCC ID : Y8PFJ17-1

Radiated Emission (Above 1GHz)




Photo 1



Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11374628H-B-R1 Page : 15 of 15

Issued date : September 7, 2016 FCC ID : Y8PFJ17-1

Worst Case Position (Horizontal: X-axis / Vertical: X-axis)

X-axis



Y-axis



Z-axis



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124