Test report No. : 10013574H-A-R1
Page : 26 of 29
Issued date : June 21, 2013
Revised date : August 9, 2013
FCC ID : Y8PFJ14-2

APPENDIX 3: Photographs of test setup

Radiated Emission Antenna (TYPE 1)



Photo 1



Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10013574H-A-R1
Page : 27 of 29
Issued date : June 21, 2013
Revised date : August 9, 2013
FCC ID : Y8PFJ14-2

Radiated Emission Antenna (TYPE 2)



Photo 1



Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10013574H-A-R1
Page : 28 of 29
Issued date : June 21, 2013
Revised date : August 9, 2013
FCC ID : Y8PFJ14-2

Worst Case Position

Antenna (TYPE 1) Below 30MHz: X Above 30MHz: Horizontal X, Vertical X X-axis



Y-axis



Z-axis



Antenna (TYPE 2)
Below 30MHz: X
Above 30MHz: Horizontal Y, Vertical Y
X-axis



Y-axis



Z-axis



UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10013574H-A-R1
Page : 29 of 29
Issued date : June 21, 2013
Revised date : August 9, 2013
FCC ID : Y8PFJ14-2

Worst Case Position

Smart ECU Below 30MHz: X Above 30MHz: Horizontal X, Vertical X X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN