Test report No. : 12047157H-B-R1
Page : 13 of 15
Issued date : April 5, 2018
FCC ID : Y8PFJ18-2

### **APPENDIX 3: Photographs of test setup**

# Radiated Emission (Below 1GHz)




Photo 1



Photo 2

# UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

 Test report No.
 : 12047157H-B-R1

 Page
 : 14 of 15

 Issued date
 : April 5, 2018

 FCC ID
 : Y8PFJ18-2

# Radiated Emission (Above 1GHz)



Photo 1




Photo 2

# UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 12047157H-B-R1 : 15 of 15 Page : April 5, 2018 : Y8PFJ18-2 **Issued date** FCC ID

Worst Case Position
(Horizontal: X-axis / Vertical: X-axis)






Y-axis



**Z**-axis



**End of Report** 

## UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124