Test report No. : 31DE0258-HO-02-A

Page : 11 of 16 Issued date : February 2, 2011 FCC ID : Y8PSSPIMB03

APPENDIX 1: Photographs of test setup

Radiated Emission



Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 31DE0258-HO-02-A

Page : 12 of 16 Issued date : February 2, 2011 FCC ID : Y8PSSPIMB03

Worst Case Position

Below 30MHz	Z-axis
Above 30MHz	Horizontal:X-axis / Vertical:X-axis

X-axis



Y-axis





UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124