Test report No. : 11995122H-R1 Page : 13 of 15

Issued date : November 17, 2017 FCC ID : Y8PFJ18-1

#### **APPENDIX 3: Photographs of test setup**

## Radiated Emission (Below 1GHz)




Photo 1




Photo 2

## UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11995122H-R1 Page : 14 of 15

Issued date : November 17, 2017

FCC ID : Y8PFJ18-1

# Radiated Emission (Above 1GHz)




Photo 1




Photo 2

### UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11995122H-R1 Page : 15 of 15

Issued date : November 17, 2017

FCC ID : Y8PFJ18-1

### Worst Case Position (Horizontal: X-axis / Vertical: X-axis)

### X-axis



Y-axis



**Z**-axis



**End of Report** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124