Page : 23 of 27

Issued date : February 24, 2012 FCC ID : Y8PSSPLF02

### **APPENDIX 3: Photographs of test setup**

# **Radiated emission**




Photo 1




Photo 2

# UL Japan, Inc.

**Head Office EMC Lab.** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 24 of 27

: February 24, 2012 : Y8PSSPLF02 Issued date FCC ID




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 25 of 27

Issued date : February 24, 2012 FCC ID : Y8PSSPLF02

## **Radiated emission**



Photo 1




Photo 2

**Head Office EMC Lab.** 


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 26 of 27


Issued date : February 24, 2012 FCC ID : Y8PSSPLF02


### **Worst Case Position**


Door Antenna
Below 30MHz:X-axis
Above 30MHz(Hori:X-axis /Vert:X-axis)





Trunk Antenna
Below 30MHz:X-axis
Above 30MHz(Hori:X-axis /Vert:X-axis)











UL Japan, Inc.

**Head Office EMC Lab.** 


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 27 of 27


Issued date : February 24, 2012 FCC ID : Y8PSSPLF02


### **Worst Case Position**

Room Antenna / Luggage Antenna Below 30MHz:-Xaxis Above 30MHz(Hori:X-axis /Vert:X-axis)




ECU
Below 30MHz:X-axis
Above 30MHz(Hori:X-axis /Vert:X-axis)











UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN