Test report No. : 10837078H-B-R1
Page : 13 of 15
Issued date : July 10, 2015
Revised date : August 3, 2015
FCC ID : Y8PFJ14-1

APPENDIX 3: Photographs of test setup

Radiated Emission

(Below 1GHz)



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

: 10837078H-B-R1 Test report No. : 14 of 15 Page : July 10, 2015 : August 3, 2015 **Issued date** Revised date FCC ID : Y8PFJ14-1

Radiated Emission (Above 1GHz)




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

: 10837078H-B-R1 Test report No. Page : 15 of 15 **Issued date** : July 10, 2015 : August 3, 2015 Revised date FCC ID : Y8PFJ14-1

Worst Case Position (Horizontal: X-axis / Vertical: X-axis)

X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124