Page
 : 11 of 28

 Issued date
 : August 8, 2011

 FCC ID
 : Y8PSSPLF04

APPENDIX 1: Photographs of test setup

Radiated emission

Door Antenna



Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 12 of 28 Issued date : August 8, 2011 FCC ID : Y8PSSPLF04

Radiated emission Trunk Antenna




Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 13 of 28 Issued date : August 8, 2011 FCC ID : Y8PSSPLF04

Radiated emission Room Antenna / Luggage Antenna



Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


: 31LE0019-HO-01-A Test report No.

Page : 14 of 28 **Issued date** : August 8, 2011 FCC ID : Y8PSSPLF04

Worst Case Position

Door Antenna Below 30MHz:X-axis Above 30MHz(Hori:X-axis /Vert:X-axis)






Door Oscillator


Below 30MHz:X-axis



Y-axis



Z-axis



Z-axis






UL Japan, Inc. **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 15 of 28 Issued date : August 8, 2011 FCC ID : Y8PSSPLF04

Worst Case Position

Trunk Antenna Below 30MHz:X-axis Above 30MHz(Hori:X-axis /Vert:X-axis)




Y-axis



Z-axis




Room Antenna / Luggage Antenna Below 30MHz:-Zaxis Above 30MHz(Hori:X-axis /Vert:X-axis)



Y-axis



Z-axis




UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Page : 16 of 28
Issued date : August 8, 2011
FCC ID : Y8PSSPLF04

Worst Case Position


ECU Below 30MHz:X-axis Above 30MHz(Hori:X-axis /Vert:X-axis)



Y-axis



Z-axis



Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN