Test report No.
 : 10835051H-B-R1

 Page
 : 13 of 15

 Issued date
 : July 21, 2015

 Revised date
 : September 17, 2015

 FCC ID
 : Y8PFJ16-1

#### **APPENDIX 3: Photographs of test setup**

#### Radiated Emission (Below 1GHz)



Photo 1



Photo 2

## UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

 Test report No.
 : 10835051H-B-R1

 Page
 : 14 of 15

 Issued date
 : July 21, 2015

 Revised date
 : September 17, 2015

 FCC ID
 : Y8PFJ16-1

# Radiated Emission (Above 1GHz)




Photo 1




Photo 2

## UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

 Test report No.
 : 10835051H-B-R1

 Page
 : 15 of 15

 Issued date
 : July 21, 2015

 Revised date
 : September 17, 2015

 FCC ID
 : Y8PFJ16-1

#### Worst Case Position (Horizontal: X-axis / Vertical: X-axis)

#### X-axis



Y-axis



**Z**-axis



**End of Report** 

### UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124