The output power of this product is below the threshold requiring RF exposure evaluation. from RF Exposure review.	This device is exempt