

開元通訊股份有限公司 InnoComm Mobile Technology Corp.

3F, No.6, HsinAnn Road, HsinChu Scenic Park, HsinChu City, Taiwan, R.O.C Tel. +886-3-5781868 / Fax. +886-3-578-1187 <u>www.innocomm.com</u>

Date:2019-12-05

Third RF port (WL3 port) No RF function Declaration

We, InnoComm mobile technology Corp., declare that The third RF port (WL3) is no RF function in model SB30.

The SOM module (model name SB30) included RF ports listed as below:

RF port	Description
WL1	MT7668 Wi-Fi 2.4G/5G / BT 2.4G
WL2	MT7668 Wi-Fi 2.4G/5G
WL 3	Reserved for MT8362 build in Wireless feature, The Wireless feature is controlled by IC firmware driver. SB30 disable MT8362 build in Wireless feature.

Should you have any questions, please contact us.

Sincerely,

Keller Lin Signature:

Name: Keller Lin

Title: PV manager

E-MAIL: keller.lin@innocomm.com

TEL: +886-3-5781868