


Report No.: TRE12040099 Page 68 of 80 Issued: 2012-06-19







Report No.: TRE12040099 Page 69 of 80 Issued: 2012-06-19






Report No.: TRE12040099 Page 70 of 80 Issued: 2012-06-19

6. External and Internal Photos of the EUT

External Photos







Report No.: TRE12040099 Page 71 of 80 Issued: 2012-06-19







Report No.: TRE12040099 Page 72 of 80 Issued: 2012-06-19









Report No.: TRE12040099 Page 73 of 80 Issued: 2012-06-19

Internal Photos






Report No.: TRE12040099 Page 74 of 80 Issued: 2012-06-19







Report No.: TRE12040099 Page 75 of 80 Issued: 2012-06-19







Report No.: TRE12040099 Page 76 of 80 Issued: 2012-06-19






Report No.: TRE12040099 Page 77 of 80 Issued: 2012-06-19







Report No.: TRE12040099 Page 78 of 80 Issued: 2012-06-19







Report No.: TRE12040099 Page 79 of 80 Issued: 2012-06-19





Report No.: TRE12040099 Page 80 of 80 Issued: 2012-06-19





.....End of Report.....