


Report No: CCIS13050012802

## **Test Setup Photo**

Radiated Spurious Emission






Telephone: +86 (0) 755 23118282 Fax: +86 (0) 755 23116366



Report No: CCIS13050012802



## 8 EUT Constructional Details

Reference to the test report No. CCIS13050012801

-----End of report-----

Telephone: +86 (0) 755 23118282 Fax: +86 (0) 755 23116366

Page 52 of 52