

page 1 of 6

ANNEX A TEST SETUP PHOTOS




113093_13.JPG: Test setup fully anechoic chamber

Examiner: Manuel BASTERT Date of issue: 27 Octob er 2011 Test Report No.: F113093E3 Annex A Order No.: 11-113093



ANNEX A TEST SETUP PHOTOS



113093_08.JPG: Test setup fully anechoic chamber


Examiner: Manuel BASTERT Date of issue: 27 Octob er 2011 Test Report No.: F113093E3 Annex A Order No.: 11-113093

page 2 of 6



page 3 of 6

ANNEX A TEST SETUP PHOTOS




113093_09.JPG: Test setup fully anechoic chamber

Examiner: Manuel BASTERT Date of issue: 27 Octob er 2011 Test Report No.: F113093E3 Annex A Order No.: 11-113093



ANNEX A TEST SETUP PHOTOS



113093_10.JPG: Test setup fully anechoic chamber

Examiner: Manuel BASTERT Date of issue: 27 Octob er 2011 Test Report No.: F113093E3 Annex A Order No.: 11-113093

page 4 of 6



page 5 of 6

ANNEX A TEST SETUP PHOTOS




113093_11.JPG: Test setup fully anechoic chamber

Examiner: Manuel BASTERT Test Report No.: F113093E3 Annex A
Date of issue: 27 October 2011 Order No.: 11-113093



page 6 of 6

ANNEX A TEST SETUP PHOTOS



113093_15.JPG: Test setup open area test site

Examiner: Manuel BASTERT Test Report No.: F113093E3 Annex A
Date of issue: 27 October 2011 Order No.: 11-113093