




110734_8.jpg Test set-up fully anechoic chamber

Test engineer: Thomas KÜHN Report Number: F110734E2, 2nd version Date of issue: 13 April 2012 Order Number: 110734

D734 page 1 of 5






110734_6.jpg Test set-up fully anechoic chamber

Report Number:F110734E2, 2nd version Order Number: 110734



page 3 of 5

ANNEX A: TEST SET-UP PHOTOGRAPHS



110734_9.jpg Test set-up fully anechoic chamber

Test engineer: Thomas KÜHN Date of issue: 13 April 2012

Report Number:F110734E2, 2nd version Order Number: 110734






110734_10.jpg Test set-up fully anechoic chamber

Report Number:F110734E2, 2nd version Order Number: 110734

Test engineer: Thomas KÜHN Date of issue: 13 April 2012

page 4 of 5





110734_17.jpg Test set-up open area test site

Test engineer: Thomas KÜHN Date of issue: 13 April 2012 Report Number:F110734E2, 2nd version Order Number: 110734