

Annex 4: Test setup photographs to TEST REPORT

No.: 17-1-0291301T01a

According to: **FCC Regulations** Part 15.209


ISED-Regulations RSS-210, Issue 9 RSS-Gen, Issue 4

for

Robert Bosch Car Multimedia GmbH

Instrument cluster with immobilizer Audi FPK Gen2 (Q3)

FCC-ID: YBN-AUFPK20 ISED: 9595A-AUFPK20 PMN: Audi FPK Gen2 HVIN: Audi FPK Gen2



CETECOM GmbH

Laboratory Radio Communications & Electromagnetic Compatibility
Im Teelbruch 116 • 45219 Essen • Germany
Registered in Essen, Germany, Reg. No.: HRB Essen 8984
Tel.: + 49 (0) 20 54 / 95 19-954 • Fax: + 49 (0) 20 54 / 95 19-964
E-mail: info@cetecom.com • Internet: www.cetecom.com

Laboratory Accreditation and Listings



		• 4	4
า วท	മെ	conte	ntc
I avi	\mathbf{v}	COME	1110

1. TEST SET UP PHOTOGRAPHS......3



Annex 1 to Test Report 17-1-0291301T01a, Page 3 of 4 1. Test set up photographs



Photograph 1: Magnetic fields measurement test set-up (overview)



Photograph 2: Radiated measurements test set-up (close view)





Photograph 3: Electrical field measurement test set-up (overview)