

Annex 2: External photographs to TEST REPORT No.: 17-1-0065901T59a A2

According to:

FCC Regulations

Part 15.205 Part 15.209 Part 15.247

IC-Regulations


RSS-Gen, Issue 4 RSS-247, Issue 2

for

Bosch Car Multimedia GmbH

AIVIP32R0

FCC-ID: YBN-AIVIP32R0 IC: 9595A-AIVIP32R0 PMN: AIVIP32R0 HVIN: AIVIP32R0 FVIN: X128



Tel.: + 49 (0) 20 54 / 95 19-954 • Fax: + 49 (0) 20 54 / 95 19-964 E-mail: info@cetecom.com • Internet: www.cetecom.com



TABLE OF CONTENTS:

1. EXTERNAL PHOTOGRAPHS	. 3
1.1. Equipment Under Test (EUT)-Radiated Test Sample	. 3
1.2. Equipment Under Test (EUT)-Conducted Test Sample	. 7



1. External photographs

1.1. Equipment Under Test (EUT)-Radiated Test Sample



Photograph 1:AIVI -Front Side



Photograph 2: AIVI -Rear Side






Photograph 3: AIVI -Top Side




Photograph 4: AIVI -Bottom Side






Photograph 5: AIVI -Right Side



Photograph 6: AIVI -Left Side





Photograph 7: AIVI -Harness



1.2. Equipment Under Test (EUT)-Conducted Test Sample



Photograph 8:AIVI -Front Side




Photograph 9:AIVI – Top Side-Connector View






Photograph 10:AIVI -Rear Side



Photograph 11:AIVI -Left Side





Photograph 12:AIVI-Power Cable